


\*OPTIONAL\*  
 .10" TRANSITION  
 PCB ASSEMBLY

A

0.025" SQ. PINS  
 2x14x.10" GRID



B

0.025" SQ. PINS  
 2x14x.10" GRID


SOCKETS  
 4x14x.05" GRID

|    |    |    |    |    |    |    |    |    |    |    |    |    |    |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 49 | 47 | 45 | 43 | 41 | 39 | 37 | 35 | 33 | 31 | 29 | 27 | NC | NC |
| 50 | 48 | 46 | 44 | 42 | 40 | 38 | 36 | 34 | 32 | 30 | 28 | 26 |    |

PINOUT OF 2 X 14  
 CONNECTOR "A"  
 ON TRANSITION BOARD

|   |   |   |   |    |    |    |    |    |    |    |    |    |    |
|---|---|---|---|----|----|----|----|----|----|----|----|----|----|
| 2 | 4 | 6 | 8 | 10 | 12 | 14 | 16 | 18 | 20 | 22 | 24 | NC | NC |
| 1 | 3 | 5 | 7 | 9  | 11 | 13 | 15 | 17 | 19 | 21 | 23 | 25 | NC |

PINOUT OF 2 X 14  
 CONNECTOR "B"  
 ON TRANSITION BOARD



EXTRACTOR  
 TOOL


PRY TO  
 REMOVE

0.015" SQ. PINS  
 4x12x.05" GRID



|    |    |    |    |    |    |    |    |    |    |    |    |    |    |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 49 | 47 | 45 | 43 | 41 | 39 | 37 | 35 | 33 | 31 | 29 | 27 | NC | NC |
| 50 | 48 | 46 | 44 | 42 | 40 | 38 | 36 | 34 | 32 | 30 | 28 | 26 | NC |
| 2  | 4  | 6  | 8  | 10 | 12 | 14 | 16 | 18 | 20 | 22 | 24 | NC | NC |
| 1  | 3  | 5  | 7  | 9  | 11 | 13 | 15 | 17 | 19 | 21 | 23 | 25 | NC |

PINOUT OF 4 X 12 CONNECTOR  
 TOP VIEW OF DELTA Probe™


DELTA PROBE™




TSOP IC  
 PACKAGE



50 TSOP DELTA PROBE



SOFT BRUSH



**Adapters-Plus** ☎ 209-839-0200  
 15 W 8TH STREET; TRACY, CA 95376

www.adapt-plus.com